

NOTE: ALTERNATE STANDARD HALF CMU WITH OMNI JAMB BLOCK AT CONTROL JOINT SAW CUT NOTCH IN OMNI JAMB BLOCK TO ACCOMMODATE RUBBER GASKET



S-801.1

